

```

SELECT
  DatumTijd,
  ROUND(Import_meterstand - LAG(Import_meterstand) OVER (ORDER BY
DatumTijd), 3) AS Import,
  ROUND(Export_meterstand - LAG(Export_meterstand) OVER (ORDER BY
DatumTijd), 3) AS Export,
  Opwek AS Opwek
FROM (
  SELECT DatumTijd,
  import_laag_meterstand + import_hoog_meterstand AS Import_meterstand,
  export_laag_meterstand + export_hoog_meterstand AS Export_meterstand
  FROM (
  SELECT datetime(s.start_ts,'unixepoch') AS DatumTijd,
  SUM(CASE WHEN s.metadata_id = 55 THEN s.state END) import_laag_meterstand,
  SUM(CASE WHEN s.metadata_id = 56 THEN s.state END)
import_hoog_meterstand,
  SUM(CASE WHEN s.metadata_id = 57 THEN s.state END) export_laag_meterstand,
  SUM(CASE WHEN s.metadata_id = 58 THEN s.state END) export_hoog_meterstand
  FROM statistics s
  WHERE s.metadata_id IN (55, 56, 57, 58)
  GROUP BY DatumTijd
  ) d
) AS foo
JOIN (
  SELECT datetime(s.start_ts,'unixepoch') AS DT,
  ROUND((s.state - LAG(s.state, 1) OVER (ORDER BY s.start_ts)), 3) AS Opwek
  FROM statistics s
  WHERE s.metadata_id = 36
) AS bar ON foo.DatumTijd = bar.DT
ORDER BY DatumTijd;

```

In dit geval had ik de volgende sensors :

36	sensor.solaredge_ac_energy_kwh	recorder	kWh
47	sensor.electricity_meter_energy_consumption_tarif_1	recorder	kWh
48	sensor.electricity_meter_energy_consumption_tarif_2	recorder	kWh
49	sensor.electricity_meter_energy_production_tarif_1	recorder	kWh
50	sensor.electricity_meter_energy_production_tarif_2	recorder	kWh
55	sensor.p1_dongle_pro_energy_delivered_t1	recorder	kWh
56	sensor.p1_dongle_pro_energy_delivered_t2	recorder	kWh
57	sensor.p1_dongle_pro_energy_returned_t1	recorder	kWh
58	sensor.p1_dongle_pro_energy_returned_t2	recorder	kWh